

# Oil Field Environmental Incident Summary

**Incident:** 20151010112839

**Date/Time of Notice:** 10/10/2015 11:28

**Responsible Party:** BURLINGTON RESOURCES OIL & GAS COMPANY LP

**Well Operator:** BURLINGTON RESOURCES OIL & GAS COMPANY LP

**Well Name:** KINGS CANYON 21-27H

**Field Name:** CAMEL BUTTE

**Well File #:** 18018

**Date Incident:** 10/9/2015

**Time Incident:** 22:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 151

**Rng:** 96

**Sec:** 27

**Qtr:** NW NE

**Location Description:**

**Submitted By:** Lewis Schoenberger

**Received By:**

**Contact Person:** Lewis Schoenberger  
PO BOX 51810  
MIDLAND, TX 79710-1810

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 2000 Feet

**Distance Nearest Water Well:** 2000 Feet

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	20	Barrels				

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None.

**Areal Extent:**

approximately 70 feet by 90 feet all on the well pad.

***Potential Environmental Impacts:***

None

***Action Taken or Planned:***

A vacuum truck has been dispatched to collect free liquids. Oil impacted gravel and debris will be collected for appropriate disposal.

***Wastes Disposal Location:***

***Agencies Involved:***

***Updates***

---

***Date:*** 10/12/2015 ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** O'Gorman, Brian

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release, due to a valve/piping connection leak, remained on facility site according to the report. NDIC retains oversight.